








①		3001____00 Barra de enrollado de 70 o 78	⑦		430013____ Guía lateral 1013
②		400136____ Perfil carga 1013	⑧		49011013000 Pasador guía llisquet
③		3502__20000 Casquillo máquina 70 o 78 13x66	⑨		49011013100 Tope guía 1013
④		3501__00000 Casquillo punta 70 o 78	⑩		39401650001 Perfil cofre 4016
⑤		470401600__ Jgo tapas laterales 4016			
⑥		550119000__ Máquina GR larga			